




drilling and positioning template



detectable
warning surface

installation template
60 buttons
(120 buttons /lm)

installation



podoinox

podobouton in
podobouton out
podobouton ABS

podotone

podotone bouton in 35
podotone bouton out 35

final disposition (linear meter)

