



**drilling and positioning template**




detectable  
warning surface

installation template  
40 buttons  
(80 buttons /lm)

**installation**



+



**podoinox**

podobouton in  
podobouton out  
podobouton ABS

**podotone**

podotone bouton in 35  
podotone bouton out 35

**final disposition (linear meter)**

